



## How to: Remove unsightly trim crease mark from gear gaitor.

You may have noticed, as I have, that there is an annoying crease in the gear lever gaitor.

I have no idea why the gear gaitor surround was designed in this way, but I didn't like the look of it, and IMO will promote the premature wear of the gear gaitor.



To fix this, I simply removed the gear knob (by pulling it off the gear lever) as well as unclipping the gear gaitor from the trim, and then cut the excess plastic off with a Dremel (or similar tool)





After refitting the gaiter, the crease is gone

